

Product Line	Service Job	Estimated Completion Time
Grinder	Jack Shaft Replacement	5 hours
Grinder	Rotor Shaft Replacement	3 hours
Grinder	Mixing Auger Replacement	2 hours, 3 hours(6105)
Grinder	Gearbox Replacement	1 hour, 2 hours(6105)
Grinder	Weighbar Replacement	1 hour
Grinder	Hyd. Motor Replacement	1/2 hour

Manure Spreader	Apron Chain Service Section Replacement	2 hours
Manure Spreader	Bearing Replacement	1 hour
Manure Spreader	Hyd Motor Replacement	1/2 hour
Manure Spreader	Weighbar or Spindle Replacement	1 hour

Forage Box	Cross Conveyor Replacement	2 hours
Forage Box	Gearbox Replacement	1 hour
Forage Box	Beater Chain Replacement	1/2 Hour
Forage Box	Hyd Motor Replacement	1/2 hour

Bale Processor	Rotor Replacement	2 hours
Bale Processor	Apron Shaft Replacement	2 hours
Bale Processor	Hyd Motor Replacement	1/2 hour
Bale Processor	Apron Chain Slat Replacement	1 hour

High Dump	Cylinder Replacement	1 hour
-----------	----------------------	--------

Land Maintenance	Bit Replacement	1 hour
Land Maintenance	Cylinder Replacement	1 hour
Land Maintenance	Caster Replacement	1-1/2 hours

Beet Equipment	Gearbox Replacement	2 hours
Beet Equipment	Hyd Motor Replacement	1/2 hour
Beet Equipment	Stub Shaft Replacement	2 hours
Beet Equipment	Lifter Wheel Replacement	1 hour
Beet Equipment	Scalper Replacement	1 hour
Beet Equipment	Cylinder Replacement	1 hour
Beet Equipment	Bearing Replacement	1 hour
Beet Equipment	belted chain replacement	3 hours